

Custom Solutions Microcontrollers

OTP/Flash Programmer Vendor Contact Information. Updated - 8/27/04. For latest information go to: www.national.com/mcu.
 Since vendor representatives change periodically, and without notice, we cannot assure you that any published listings would be current and without error. Please contact the vendor's home office, or web page, for assistance if you are having problems locating a representative.

| Vendor | Home Office | Electronic Sites | Additional Main Offices |
|-----------------|-----------------------------------------------------------------------|------------------------------------------------------------------------|-------------------------|
| BP Microsystems | *USA: Houston, Tx. 800-225-2102 713-688-4600, fax: 713-688-0920 | bbs: 713-688-9283 www.bpmicro.com sales@bpmicro.com | |
| HI-LO | *Taiwan: Taipei 886-2-87923301 fax: 886-2-87923285 | www.hilosystems.com.tw sales@hilosystems.com.tw bbs: 2-2769-0881 | Tribal (USA) |

| Adapters | Home Office | Electronic Sites | Adapters Supported |
|----------|----------------------------------------------------------|----------------------------------------------------|----------------------------------------------------------------|
| HI-LO | *Taiwan: Taipei 886-2-87923301 fax: 886-2-87923285 | www.hilosystems.com.tw sales@hilosystems.com.tw | COP8 44QFP adapter; COP8 CSP/LLP Adapters; COP8FLASH adapters; |

Adapter specifications available from our web site page at: <http://www.national.com/appinfo/mcu/0,3189,577,00.html>