



$$V_{T1} = \frac{(4.1V)R2}{R2 + R1 \parallel R3}$$

$$V_{T2} = \frac{(4.1V)R2}{R2 \parallel R3 + R1}$$